PURCHASE ORDER

TEXAS A&M FOREST SERVICE PURCHASING DEPARTMENT

Order Date 01/15/2025

Page 01

200 Technology Way, Suite 1120, College Station, TX 77845-3424; Phone 979-458-7380, FAX 979-458-7386

Purchase Order (Include this number on all INVOICE TO: correspondence and packages) VENDOR GUARANTEES MERCHANDISE DELIVERED ON TEXAS A&M FOREST SERVICE THIS ORDER WILL MEET OR P500225 EXCEED SPECIFICATIONS IN MERKEL OFFICE PO BOX 429 MERKEL TX 79536 THE BID INVITATION. **VENDOR** ALL TERMS AND CONDITIONS SET FORTH IN OUR BID 17509728254 SHIP TO: INVITATION BECOME BRUCKNER TRUCK SALES INC A PART OF THIS CORPORATE BILLING LLC DEPT 100 TEXAS A&M FOREST SERVICE ORDER. PO BOX 830604 BURKBURNETT OFFICE BIRMINGHAM, AL 35283-0604 1900 S. FM 369 BURKBURNETT TX 76354

ANY EXCEPTIONS TO PRICING OR DESCRIPTION CONTAINED HEREIN MUST BE APPROVED BY THE TEXAS A&M FOREST SERVICE PURCHASING DEPARTMENT <u>PRIOR</u> TO SHIPPING.

PLEASE NOTE: IF YOUR INVOICE IS NOT ADDRESSED AS INSTRUCTED PAYMENT WILL BE DELAYED.

	BY THE TEXAS A&M FOREST SERVICE PURCHASING DEPARTMENT PRIOR TO SHIPPING.	P	AYMENT WIL	L BE DELAYED.	
Item	Description	Quantity	UOM	Unit Price	Ext Price
1	USER REF: 000000-SSP Bruckner's Truck&Equip 12/17-12/31/24 Burkburnett unit 1770/lp#1180177/asset#25075 Service:Radiator repair, repair air leaks, repair engine oil leaks, rear main seal repair	1	EA	18,519.320	18,519.32
	, , , , , , , , , , , , , , , , , , ,			TOTAL	18,519.32
	**** NET 30 ****				
	NOTE TO VENDOR: "SHIP TO" AND "INVOICE TO" ADDRESSES MAY DIFFER. FAILURE TO SUBMIT INVOICE TO PROPER ADDRESS MAY RESULT IN DELAYED PAYMENT.			į	
	EXEMPTION: INDETERMINANT INTERNAL REPAIRS				
	ALL REPLACEMENT PARTS USED IN THE REPAIRS ARE TO BE NEW OR REFURBISHED.				
	BY ACCEPTANCE OF THIS PURCHASE ORDER VENDOR AGREES TO ALL TERMS AND CONDITIONS (AS APPLICABLE) LISTED ON ATTACHED "TEXAS A&M FOREST SERVICE PURCHASE ORDERATTACHMENT A".		ı.		
;	EXEMPT INDETERMINANT REPAIRS TO AGENCY FLEET VEHICLE. AGENCY TERMS AND CONDITIONS SHALL APPLY.	į			
	VENDOR QUOTE: 19079506 VENDOR REF: SERVICE INVOICE RA105008542:01				
	Purchase made by an Institution of Higher Education, Section 51.9335 Education Code.				
RTL					
Texas A&	M Forest Service cannot accept collect freight shipments.				· · · · · · · · · · · · · · · · · · ·

Texas A&M Forest Service cannot accept collect freight shipments.

FOB: NOT SPECIFIED

Terms:

IN ACCORDANCE WITH YOUR BID, SUPPLIES/EQUIPMENT MUST BE PLACED IN THE DEPARTMENT RECEIVING ROOM BY

FAILURE TO DELIVER - If the vendor fails to deliver those supplies by the promised delivery date or a reasonable timo thereafter, without giving acceptable reasons for delay, or if supplies are rejected for failure to meet specifications, the State reserves the right to purchase specified supplies elsewhere, and charge the increase in price and cost of handling, if any, to the vendor. No substitutions nor cancellations permitted without prior approval of Purchasing Department.

THIS ORDER IS NOT VALID UNLESS SIGNED BY THE PURITH

ATTO HOT VILLO CHECO CICILEO DI VILLO

PURCHASING AGENT FOR

TEXAS A&M FOREST SERVICE

The State of Texas is exempt from all Federal Exciso Taxes.

STATE AND CITY SALES TAX EXEMPTION CERTIFICATE: The undersigned claims an exemption from taxes under Texas Tax Code, Section 151.309 (4), for purchase of tangible personal property described in this numbered order, purchased from contractor and/or shipper listed above, as this property is being secured for the exclusive use of the State of Texas.

The Terms and Conditions of the State of Texas shall prevail.

RECEIVING

TEXAS A&M FOREST SERVICE PURCHASING DEPARTMENT

Order Date 01/15/2025

Page 02

200 Technology Way, Suite 1120, College Station, TX 77845-3424; Phone 979-458-7380, FAX 979-458-7386

Purchase Order (Include this number on all correspondence and packages)	VENDOR	GUARANTEES	INVOICE TO:
P500225	MERCHA THIS ORI EXCEED	NDISE DELIVERED ON DER WILL MEET OR SPECIFICATIONS IN INVITATION.	TEXAS A&M FOREST SERVICE MERKEL OFFICE PO BOX 429 MERKEL TX 79536
VENDOR		ALL TERMS AND CONDITIONS SET	
17509728254		FORTH IN OUR BID	SHIP TO:
BRUCKNER TRUCK SALES INC CORPORATE BILLING LLC DEPT 100 PO BOX 830604 BIRMINGHAM, AL 35283-0604		A PART OF THIS ORDER.	TEXAS A&M FOREST SERVICE BURKBURNETT OFFICE 1900 S. FM 369 BURKBURNETT TX 76354

ANY EXCEPTIONS TO PRICING OR DESCRIPTION CONTAINED HEREIN MUST BE APPROVED
BY THE TEXAS ARM EXPECT SERVICE PURCHASING DEPARTMENT PRIOR TO SHIPPING.

PLEASE NOTE: IF YOUR INVOICE IS NOT ADDRESSED AS INSTRUCTED

	BY THE T	EXAS A&M FC	DREST SERVICE PURCHASING DEPARTMENT	PRIOR TO SHIPPING.	P	AYMENT WIL	L BE DELAYED.	
Item			Description		Quantity	UOM	Unit Price	Ext Price
	CC	FY	ACCOUNT NO.	DEPT.				
	11	2025	112003-00000-5511	RPAD			18,519.32	
	מססמ	MENT D	ATE: 01/15/2025					
	DEPT PHON	C.CONTA	CT:					
	PCC	CD: 9						
	TYPE	E FUND:	TYPE ORDER:					
	ļ							
	ļ 							
						1		
RTL	<u> </u>					<u> </u>		

Texas A&M Forest Service cannot accept collect freight shipments.

NOT SPECIFIED FOB:

Terms:

FAILURE TO DELIVER - If the vendor fails to deliver these supplies by the promised delivery date or a reasonable time thereafter, without giving acceptable reasons for delay, or if supplies are rejected for failure to meat specifications, the State reserves the right to purchase specified supplies elsewhere, and charge the increase in price and cost of handling, if any, to the vendor. No substitutions nor cancellations pormitted without prior approval of Purchasing Department.

IN ACCORDANCE WITH YOUR BID, SUPPLIES/EQUIPMENT MUST BE PLACED IN THE DEPARTMENT RECEIVING ROOM BY

THIS ORDER IS NOT VALID UNLESS SIGNED BY THE PURCHASING

PURCHASING AGENT FOR

STATE AND CITY SALES TAX EXEMPTION CERTIFICATE: The undersigned claims an exemption from taxes under Texas Tax Code, Section 151.309 (4), for purchase of tangette personal property described in this numbered order, purchased from contractor and/or shipper listed above, as this property is being secured for the exclusive use of the State of Texas.

The Terms and Conditions of the State of Texas shall prevail.

The State of Toxas is exempt from all Federal Exciso Taxes.

TEXAS A&M FOREST SERVICE

IMPORTANT PAYMENT NOTICE - Remit payment to: Corporate Billing LLC Dept 100 Po Box 830604 Birmingham, AL 35283 Payment to any other party does not constitute payment.



4520 NORTHWEST FWY WICHITA FALLS, TX 76306 P: (940) 855-4051 www.brucknertruck.com

SERVICE INVOICE: RA105008542:01

REFERENCE: 19079506

Tag Number:

Customer Unit#: 1770



BILL TO **TEXAS FOREST SERVICE - 159926** 610 NORTH IST ST PO BOX 429 MERKEL TX 79536 P: (325) 928-1427

TEXAS FOREST SERVICE - 159926 610 NORTH IST ST PO BOX 429 MERKEL TX 79536 P: (940) 283-4360

SERVICE INVOICE: RA105008542:01

REFERENCE: 19079506

						* * * * * * * * * * * * * * * * * * * *	
DATE	ARRIVED	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOM	ER PO#
12/17/2024		12/31/2024	SRM	D. Rusk	CB		
YEAR	MAKE	MODEL	VIN	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2015	MACK	600	LM1AN07Y0FM021322	2,998	2/26/2015		70460

Sold Operations

JOB #1 261

SERVICE - RADIATOR REPAIR

COMPLAINT

R&R RADIATOR -

CAUSE CORRECTION

REPORT RADIATOR LEAKING, VERIFIED LOWER CAP ON RADIATOR IS CRACKED, DRAINED THE REMAINING AMOUNT OF COOLANT, REMOVED OVERFLOW TANK, UNBOLTED AND MOVED THE A/C CONDENSER TO THE SIDE, REMOVED CHARGE AIR PIPING, UPPER/LOWER RADIATOR HOSES AND TRANS OIL COOLER LINES, USED OVERHEAD HOIST AND REMOVED THE COMPLETE COOLING PACKAGE, REMOVED THE CHARGE AIR COOLER FROM COOLING PACK, REMOVED THE RADIATOR OUTER FRAME AND INSTALLED IT ON THE NEW RADIATOR, INSTALLED THE TRANS OIL COOLER FITTINGS IN NEW RADIATOR, REINSTALLED THE CHARGE AIR COOLER, RAISED AND INSTALLED COMPLETE COOLING COOLING PACK, REINSTALLED CHARGE AIR HOSES, RADIATOR HOSES, TRANS OIL COOLER LINES, CONDENSER AND EXPANSION TANK, REFILLED SYSTEM WITH NEW COOLANT, CHECKED TRANS OIL LEVEL, GOOD, RAN AND CHECKED FOR COOLANT LEAKS, NONE FOUND, TOOK TO STEAM BAY AND PRESSURE WASHED THE TRUCK.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 261	R&R RADIATOR		1,080.00
1	105X/2400213-WF1.	RADIATOR	526.93	526.93
12	105M/4771-AFC11100F	RED ELC 50/50	8.12	97.44
1	105V/85131659	COLLAR	6,06	6.06
1	105V/85129501	CLIP	6.71	6.71
1	105M/21866819	O-RING	6.94	6.94

Prepay: \$0.00 Parts: \$644.08 Labor: \$1,080.00 FRT: \$0.00 Misc: \$0.00 Sublet: \$0.00

\$1,724.08

RECEIVED EMAILED MAILED

JAN 0 6 2025

MERKEL FRP

SERVICE INVOICE: RA105008542:01

REFERENCE: 19079506

Sold Operations (Cont.)

JOB #2 530

SERVICE - REPAIR AIR LEAKS

COMPLAINT

530- REPAIR AIR LEAKS- -

CAUSE

CORRECTION

FOUND MULTIPLE AIR LEAKS AT MULTIPLE FITTING ON AIR TANKS, REMOVED ALL LEAKING FITTING AND

INSTALLED NEW, RECHECKED FOR LEAKS, NO AUDIBLE AIR LEAKING FOUND.

aty	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRIC
1	105M/20999388	ELBOW NIPPLE	27.73	27.73
- 1	105M/20999384	ELBOW NIPPLE	28.61	28.61
3	105V/20999385	ELBOW NIPPLE	28,93	86.79
ı	105X/HBV038-WF	3/8 BALL VALVE	16.63	16.63
ı	105M/24500695	LUBRICANT	. 46.97	46.97
	LABOR 530	530- REPAIR AIR LEAKS-		360,00

Prepay: \$0.00 Parts: \$206,73 Labor: \$360.00 FRT: \$0.00 Mise: \$0.00 Sublet: \$0.00 \$566.73

SERVICE INVOICE: RA105008542:01

REFERENCE: 19079506

Sold Operations (Cont.)

JOB #3 232 SERVICE - REPAIR ENGINE OIL LEAKS

COMPLAINT
CAUSE
CORRECTION

232- REPAIR ENGINE OIL LEAKS-BTS -RESEAL TIMING PLATE

FOUND OIL LEAKING ON PASSENGER SIDE OF ENGINE, VERIFIED OIL LEAKING WHERE THE TIMING PLATE AND CYLINER HEAD MEET, WILL NEED TO REMOVE AND RESEAL THE LEAKING REAR ENGINE TIMING PLATE. CUSTOMER WAS NOTIFIED AND APPROVED REPAIR. PULLED TRUCK INTO SHOP. DRAINED ENGINE FLUIDS, REMOVED DRIVE LINE, TRANSMISSION, AIR COMPRESSOR, P/S TANDEM PUMP, COOLANT PIPING, OIL PAN, OIL PIPING, FLYWHEEL, AND HOUSING.REMOVED ALL GEARS TO REMOVE TIMING PLATE. REMOVED TIMING PLATE AND INSPECTED. CLEANED AND INSPECTED ALL PARTS FOR REUSE. REAR TIMING GEAR PLATE SEAL HAD A FLAT SPOT. WILL NEED TO REPLACE. INSTALLED NEW TIMING GEAR PLATE AND AJDUSTED AS NEEDED. REINSTALLED ALL GEARS, TIMED, AND ADJUSTED FOR BACKLASH AS NEEDED. TORQUED ALL BOLTS. REINSTALLED FLYWHEEL HOUSING, TRANSMISSION, AND ALL OTHER PARTS REMOVED FOR REPAIR. REPLACED GASKETS/ SEALS/ HARDWARE AS NEEDED. FILLED ENGINE WITH OIL AND COOLANT. TRUCK HAD A SOLO CLUTCH AND IS NOT OPERATING PROPERLY. THIS IS AN ISSUE AT TIMES WITH SOLO CLUTCHES. TRIED TO ADJUST BUT WOULD NOT RETURN TO SET PLACE. THE TRUCK WILL NEED A NEW CLUTCH. CUSTOMER APPROVED. REMOVED TRANSMISSION ONCE MORE. REMOVED CLUTCH AND REPLACED. REINSTALLED TRANSMISSION AND ALL ITEMS REMOVED TO PERFORM REPAIR.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 232	232- REPAIR ENGINE OIL LEAKS-BTS		9,000.00
1	105M/22190294	TIMING GEAR PLATE	651.23	651.23
1	105M/22992289	TIMING GEAR COVER	335.19	335.19
1	105M/22986942	FLYWHEEL HOUSING	1,733.34	1,733.34
2	105M/1547252	SEALING RING	13.18	26.36
6	105M/20483919	HEX. SOCKET SCREW	4.87	29,22
ı	105M/20504408	V-CLAMP	75.81	75.81
1	105M/20579690	SEALING RING	10.77	10.77
2	105M/20841816	GASKET	15.65	31.30
1	105V/20850815	GASKET	52.53	52.53
1	105M/20966752	O-RING	12.75	12.75
1	105V/21096684	O-RING	4.16	4.16
2	105M/21532261	SEALING RING	13.46	26.92
ı	105M/21780376	SEALING RING	16.22	16.22
i	105M/22191895	CRANKSHAFT SEAL	131.69	131.69
2	105M/22777560	GASKET	399.92	799.84
2	105M/24070065	CLAMP	58.95	117,90
-1	105V/24425938	NOISE SHIELD	30.29	30.29
1	105M/24533210	GREASE	23.46	23.46
1	105V/471708	RUBBER MOULDING	7,87	7.87
6	105V/8192804	FLANGE SCREW	5,32	31.92
1	105V/943177	O-RING	4.71	4.71
1	105V/21293367	SEALING STRIP	179.12	179.12
2	105M/23658111	OIL FILTER	21.62	43,24
ı	105M/21707135	OIL FILTER	38.21	38.21
38	105M/9853-M15W40BULK	MACK ENGINE OIL EOS-4.5 1	5.91	224.58
1	105M/24016949	SEALANT	20,05	20.05
1	FRT	FREIGHT	26.07	26.07
1	105M/967343	O-RING	15.78	15.78
29	105M/994447	FLANGE SCREW	5.41	156.89
6	105V/990810	FLANGE SCREW	8.61	51.66
3	105M/1147-4820	CHLORINATED BRAKE CLEANER	5.62	16.86
2	105M/992065	O-RING	19.81	39.62
l	105M/977030	O-RING	18.24	18.24
	105M/85132551	KIT	11.84	23.68

SERVICE INVOICE: RA105008542:01

REFERENCE: 19079506

		Sold Operations (Cont.)		
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	105V/20733354	CLIP	7.13	7.13
1	105V/20512915	BEARING	82.08	82.08
1	105M/8070265	CLUTCH BRAKE	30.42	30.42
1	105M/23005335	СLUТСН	1,851.40	1,851.40
		18 V		******

Prepay: \$0.00 Parts: \$6,952.44 Labor: \$9,000.00 FRT: \$26.07 Misc: \$0.00 Sublet: \$0.00

\$15,978.51

JOB #4 100

SERVICE - GENERAL REPAIR

COMPLAINT

REWORK - REAR MAIN SEAL

CAUSE

CORRECTION

REWORK ON TECH 5726- DAMAGED REAR MAIN SEAL DURING INSTALL

lı	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
ll	1	I05M/22191895	CRANKSHAFT SEAL		

Prepay: \$0.00 Parts: \$7,803.25 Labor: \$10,440.00 FRT:\$26.07 Misc: \$0.00 Su \$18,269.32 **Sold Operations Totals**

DISCLAIMER OF WARRANTIES

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTH STITHLR EXPRESS OR IMPLIED ENCLUDING ANY IMPERED WARRANTY OR MERCHANTABILITY OR ETENESS FOR A PARTICULAR PURPOSE AND BRUCKNER TRUCK SALES, INC., NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY EIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. WE HERE BY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7, AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938. AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED. UNDER SECTION 14 THEREOF

SIGNATURE OF PERSON RESPONSIBLE OR AGENT FOR PERSON RESPONSIBLE FOR PAYMENT

	ESTIMATED	RILLED
LABOR		\$10,440.00
PARTS		\$7,803.25
MISC		\$0,00
FREIGHT		\$26.07
SUBLET		\$0.00
PREPAY		\$0.00
SUBTOTAL		\$18,269.32
SHOP SUPPLIES		\$250.00
MISC SUPPLIES		\$0.00
TAX		\$0.00
TOTAL		\$18,519.32

Please Remit Payment to: Bruckner's Truck & Equipment Corporate Billing LLC Dept 100 P.O. Box 830604 Birmingham, AL 35283



Vendor Verify Report

Searched By: Lindsay Clark

Search Date: 12/20/2024 8:21:18 AM

Search String: bruckner's

Number of Results: 0

Source Name	URL	Source ID Count	Count
Texas Comptroller Vendor Hold	https://fmcpa.cpa.state.tx.us/tpis/servlet/TPISReports	1	0
Federal Excluded Parties	https://sam.gov/data-services/Exclusions/Public%20V2?privacy=Public	2	0
Debarred Vendor List	https://comptroller.texas.gov/purchasing/programs/vendor-performance-tracking/debarred-vendors.php	က	0
Divestment Statute Lists: Companies that Boycott Israel	https://comptroller.texas.gov/purchasing/docs/anti-bds.xlsx	4	0
Divestment Statute Lists: Designated Foreign Terrorist Organizations	https://comptroller.texas.gov/purchasing/docs/foreign-terrorist.xlsx	ις.	0
Divestment Statute Lists: Scrutinized Companies with ties to Iran	https://comptroller.texas.gov/purchasing/docs/iran-list.xlsx	9	0
Divestment Statute Lists: Financial Companies that Boycott Energy Companies	https://comptroller.texas.gov/purchasing/docs/divest-energy.xlsx	7	0
Texas Comptroller Vendor Hold	https://fmx.cpa.texas.gov/fmx/payment/	Φ	0
Divestment Statute Lists: Scrutinized Companies with ties to Sudan	https://comptroller.texas.gov/purchasing/docs/sudan-list.xlsx	11	0

Search String: bruckner's

Source Name	URL	Source ID Count	Count
Divestment Statute Lists: Scrutinized	https://comptroller.texas.gov/purchasing/docs/fto-list.xlsx	12	0
Companies with ties to Foreign Terrorist			
Organizations			

Search Date: 12/20/2024 8:21:18 AM