VENDOR

17427652260

PO BOX 60662

MIDLAND, TX

DBA WARREN CAT

PURCHASE ORDER

TEXAS A&M FOREST SERVICE

Page 01

PURCHASING DEPARTMENT

200 Technology Way, Suite 1120, College Station, TX 77845-3424; Phone 979-458-7380, FAX 979-458-7386 (Include this number on all No. correspondence and packages) P000448

WARREN POWER & MACHINERY INC

VENDOR GUARANTEES MERCHANDISE DELIVERED ON THIS ORDER WILL MEET OR EXCEED SPECIFICATIONS IN THE BID INVITATION.

ALL TERMS AND CONDITIONS SET FORTH IN OUR BID INVITATION BECOME A PART OF THIS ORDER.

INVOICE TO: TEXAS A&M FOREST SERVICE GRANBURY OFFICE PO BOX 69 GRANBURY TX 76048

SHIP TO:

TEXAS A&M FOREST SERVICE CHILDRESS OFFICE 610 18TH ST N.W. CHILDRESS TX 79201

ANY EXCEPTIONS TO PRICING OR DESCRIPTION CONTAINED HEREIN MUST BE APPROVED BY THE TEXAS A&M FOREST SERVICE PURCHASING DEPARTMENT PRIOR TO SHIP

79711-0662

PLEASE NOTE: IF YOUR INVOICE IS NOT ADDRESSED AS INSTRUCTED

Item	PRIOR TO SHIPPING.	PAYMENT WILL BE DELAYED.				
пеш	Description	Quantity	UOM	Unit Price	Ext Price	
	USER REF: 000000-VKM					
1	Repair work on Dozer Unit 9991	1	LOT	17,964.850	17,964.8	
				WENTER -		
				TOTAL	17,964.8	
	**** NET 30 ****					
	NOTE TO VENDOR:					
	"SHIP TO" AND "INVOICE TO" ADDRESSES MAY DIFFER. FAILURE TO SUBMIT INVOICE TO PROPER					
	ADDRESS MAY RESULT IN DELAYED PAYMENT.					
	EXEMPTION: INDETERMINANT INTERNAL REPAIRS					
	REPAIRS TO DOZER UNIT 9991					
	INVOICE #LB97924					
	VENDOR QUOTE: LB97924					
	VENDOR REF: WARREN CAT AT 866-292-7736 PHONE: 512-415-6946					
	Purchase made by an Institution of Higher Education, Section 51.9335 Education Code.					
	CC FY ACCOUNT NO. DEPT.					
	11 2020 124185-00113-5514 RESP			17,964.85		
	DOCUMENT DATE: 08/13/2020			17,904.85		
1	N. C. W. C. C. C. W. Decorption					
	DEPT.CONTACT: VANESSA MOORE PHONE NO.: 817-753-0851					
	PCC CD: 9					
OCT						
exas A&N	Forest Service cannot accept collect freight shipments.					

M Forest Service cannot accept collect freight shipments DESTINATION FRT INCLUDED

FAILURE TO DELIVER - If the vendor fails to deliver these supplies by the promised delivery date or a reasonable time thereafter, without giving acceptable reasons for delay, or if supplies are rejected for failure to meet specifications, the State reserves the right to purchase specified supplies elsewhere, and charge the increase in price and cost of handling, if any, to the vendor. No substitutions nor cancellations permitted without prior approval of Purchasing Department.

IN ACCORDANCE WITH YOUR BID, SUPPLIES/EQUIPMENT MUST BE PLACED IN THE DEPARTMENT RECEIVING ROOM BY

The State of Texas is exempt from all Federal Excise Taxes.

FOB:

STATE AND CITY SALES TAX EXEMPTION CERTIFICATE: The undersigned claims an exemption from taxes under Texas Tax Code, Section 151.309 (4), for purchase of tangible personal property described in this numbered order, purchased from contractor and/or shipper listed above, as this property is being secured for the exclusive use of the State of Texas.

The Terms and Conditions of the State of Texas shall prevail.

THIS ORDER IS NOT VALID UNLESS SIGNED BY THE PURCHASING AGENT

Terms:



TEXAS A&M FOREST SERVICE



REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Bill To:

TEXAS FOREST SERVICE FRP PO BOX 429 MERKEL TX 79536

Ship To:

SERVICE INVOICE

INVOICE NUMBER:

LB97924

Invoice Date: Due

08-11-20 \$17,964.85

Make

AA

Model

D6NXL VPAT *CAT00D6NPMLW00160

Serial # Equip No

Machine ID

Meter Reading

C41208

PSO/WO

1261.0 LB97924

		Description		Unit Dries		
	Item	07-13-20	099	G	02	2
8950685 PO REQUIRED	07 40 40	alon W	THE RESERVE AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN	OTO E	Terms	
		Doc Date	Salesman	Division	Store	
Customer # PO #						

PROFORMA INVOICE

CLEAN & INSPECT MACHINE

REPAIR PROCESS COMMENTS:

REMOVED COVERS TO ACCESS AREAS THAT WOULD NEED TO

BE WORKED ON

WASHED ALL DIRT AND DEBRIS FROM AROUND ALL CYLINDERS, TRACKS, AND CAB OF MACHINE

SEGMENT 00 TOTAL

F/R LBR

540.00 *

540.00 T

REMOVE & INSTALL

4336 AJP 7-15-20 1260 HOURS

ARRIVED TO MACHINE

VERIFIED HYD LEAK ON RIGHT FRONT CYL REMOVED PANELS

FOUND HYD LINE FOR LIFT CYLINDER LEAKING

CUSTOMER STATED THEY WILL DELIVER MACHINE TO SHOP

FOR FURTHER REPAIRS

ORDERED PARTS

REPAIR PROCESS COMMENTS:

REMOVED THE HYDRAULIC LINES TO THE TWO LIFT CYLINDERS AND INSTALLED CAPS AND PLUGS TO AVOID

AND DIRT ENTRY INTO THE SYSTEM REMOVED THE PINS HOLDING THE CYLINDERS USED THE CRANE TO REMOVE THE CYLINDERS

INSTALLED THE CYLINDER ONTO THE MACHINE INSTALLED THE HYDRAULIC LINES GREASED THE CYLINDERS 5 3D-2824

3K-0360

SEAL O RING SEAL

5

2.33

BY:

11.65



79536

BIII To:

PO BOX 429

MERKEL TX

REMITTO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

SERVICE INVOICE

INVOICE NUMBER: LB97924 Invoice Date: 08-11-20

Due \$17,964.85

AA Model D6NXL VPAT Serial # *CATOOD6NPMLW00160 Equip No

Make

Machine ID C41208

Meter Reading 1261.0

Customer#	200			PSO/WO			LB979;
950685	PO REQUIRED	Doc	Date	Salesman	Division	Store	Terms
	The Control of the Co	07-13	3-20	099	G	02	2
Quantity	Item	Description			Unit Pric	-	
16 10 5 10 5 1	6V-8398 6V-9509 6V-9746 6V-9830 7J-9108 9T-8578 3096932X	PLUG AS SEAL FILTER OILCAT HYDRO, 1 GLS		7. 1. 7.	56 33 74 43 65 71	2 7 7 4	4.96 3.30 8.70 4.30 8.25 9.71 9.00
		TOTAL PARTS	SEG	G. 01		41	8.37 *
1.0	00	SUPPLY CHARGE	F	7/R LBR			5.00 * 0.00
		TOTAL MISC CHGS		. 01		2	0.00 *
		SEGMENT 01 TOTA	L			273	3.37 T

RESEAL

REPAIR PROCESS COMMENTS:
REMOVED THE HEADS FROM BOTH CYLINDERS
REMOVED THE ROD ASSEMBLIES AND REMOVED THE PISTONS
AND HEADS FROM THE RODS
REMOVED ALL SEALS AND INSPECTED ALL COMPONENTS FOUND NO PROBLEMS INSTALLED NEW SEALS, AND INSTALLED THE HEADS AND PISTONS ONTO THE RODS
TORQUED THE BOLTS AND INSTALLED THE ROD ASSEMBLIES
BACK INTO THE BARRELS REMOVED THE BUSHINGS FROM THE PIN BORES AND INSTALLED NEW ONES

1 15-3311 1 8T-5668 4 096-7033 2 241-7584	RING RING WEAR PIN SPLIT SEAL KIT	N S N	16.10 10.90 .59 127.69	16.10 10.90 2.36 255.38
--	--	-------------	---------------------------------	----------------------------------



79536

BIII To:

PO BOX 429

MERKEL TX

REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

SERVICE INVOICE

INVOICE NUMBER: LB97924 Invoice Date: 08-11-20

Due \$17,964.85

Make AA Model D6NXL VPAT Serial # *CATOOD6NPMLW00160

Equip No Machine ID

C41208 Meter Reading 1261.0

ustomer#	PO#			PSO/WO			LB9
950685	PO REQUIRED	Doc D		Safesman	Division	Store	Terms
Quantity	Item	07-13	20	099	G	02	2
((91)	Description			Unit Price	-	Extensio	
	TOTAL PARTS	SEG.	02		284	4.74	
1.00		EMERGENCY CHARGE	F/1	R LBR			5.00 ×
	TOTAL MISC CHGS	SEG.	02			.91 *	
		SEGMENT 02 TOTA	4			961	.65 T

REMOVE & INSTALL TILT CYLINDER

REPAIR PROCESS COMMENTS: REMOVED THE HYDRAULIC LINES TO THE TWO TILT CYLINDERS AND INSTALLED CAPS AND PLUGS TO AVOID AND DIRT ENTRY INTO THE SYSTEM REMOVED THE PINS HOLDING THE CYLINDERS USED THE CRANE TO REMOVE THE CYLINDERS

INSTALLED THE CYLINDER ONTO THE MACHINE INSTALLED THE HYDRAULIC LINES GREASED THE CYLINDERS

TOTAL LABOR

SEG. 03

810.00 *

SEGMENT 03 TOTAL

810.00 T

RESEAL TILT CYLINDER

REPAIR PROCESS COMMENTS:

REMOVED THE HEADS FROM BOTH CYLINDERS REMOVED THE ROD ASSEMBLIES AND REMOVED THE PISTON AND HEADS FROM THE RODS REMOVED ALL SEALS AND INSPECTED ALL COMPONENTS



Bill To:

REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

TEXAS FOREST SERVICE FRP PO BOX 429 MERKEL TX 79536

INVOICE NUMBER: Invoice Date:	LB97924 08-11-20
Due	\$17,964.85
Make	AA
Model	D6NXL VPAT
Serial #	*CATOOD6NPMLW00160
Equip No	
Machine ID	C41208
Meter Reading	1261.0
PSOMO	LB97924
i	

SERVICE INVOICE

50685 Quantity	PO REQUIRED			1001	wo			L	B97	
Quantity	THE RESERVE OF THE PERSON NAMED IN COLUMN 1	Doc Date		Doc Date		sman	Division	n Store		ms
	Item	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	07-13-20	099		G	02		IIIS	
	nem	Descri	ption			Unit Price	02	2 Exten		
TORQUED BACK INT REMOVED INSTALLE 4 2H- 3 4D-	THE BOLTS AND	ND INSTALLED THE H INSTALLED THE ROD ROM THE PIN BORES RING BEARING	ASSEMBLIES AND S N		7.94 68.81			.76		
		KIT-SEAL-H.C TOTAL PARTS	N SE	G. 04	103.75		206 207 445	.50	4	
		SEGMENT 04	TOTAL	F/R LBF	t		675 1120	00	*	

E PIN OUT THE REST OF THE WAY WITH A SLEDGE HAMMER

ORDERED A NEW PIN FOR THE ROD END CLEANED THE BORES FOR THE PIN LINES UP THE CYLINDER ROD END AND INSTALLED THE

PIN AND KEEPER
GREASED THE PIN AND CYLINDER
1 7J-1309
1 104-4817
PIN BEARING N PIN

142.32 Go Paperless. Receive statements and invoices online 24/7. Register at www.warrencat.com/gopaperless

N

WE APPRECIATE YOUR BUSINESS. Your business is important to us and we strive to be your dealership of choice. If we did not meet your expectations, please call 866.2WARREN.

Terms of Payment: Unless specific terms of payment are stated above, which shall be the governing terms hereof, this invoice shall otherwise be due and payable in full 30 days from the invoice date. Performance under this invoice along with jurisdiction and venue shall be in Midland County, Texas. Return parts must be accompanied by the packing list or this invoice. Refer to packing list for parts return and available at http://www.warrencat.com/lerms-conditions or upon request.

142.32



79536

Bill To:

PO BOX 429

MERKEL TX

REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

SERVICE INVOICE

INVOICE NUMBER: LB97924 Invoice Date: 08-11-20

Due \$17,964.85

Make AA Model D6NXL VPAT Serial # *CATOOD6NPMLW00160 Equip No

Machine ID C41208 Meter Reading 1261.0

PSO/WO LB97924

Customer#	PO#					LB979	
8950685	PO REQUIRED	Doc Date	Salesman	Division	Store	Terms	
Quantity	Item	07-13-20	099	G	02	2	
		Description		Unit Price)	Extension	

TOTAL PARTS

SEG. 05

302.35 *

SEGMENT 05 TOTAL

F/R LBR

1080.00 * 1382.35 T

RESEAL SHIFT CYLINDER SIDE

REPAIR PROCESS COMMENTS:

REMOVED THE HEAD FROM THE CYLINDER REMOVED THE ROD ASSEMBLY AND REMOVED THE PISTON AND HEAD FROM THE ROD REMOVED ALL SEALS AND INSPECTED ALL COMPONENTS FOUND NO PROBLEMS INSTALLED NEW SEALS, AND INSTALLED THE HEAD AND PISTON ONTO THE ROD TORQUED THE BOLT AND INSTALLED THE ROD ASSEMBLY BACK INTO THE BARREL REMOVED THE BUSHINGS FROM THE PIN BORES AND INSTALLED NEW ONES

1	1U-4049 4J-4606 175-7905 225-3281 289-2937 289-2948 495-8215	WASHER RING RING SEAL-O-RING SEAL-WIPER SEAL AS SEAL U SEAL AS	ZZSSSSSZ		36.47 6.20 31.57 5.71 20.97 24.64 18.57 42.33	36.47 6.20 31.57 5.71 20.97 24.64 18.57 42.33
		TOTAL PARTS		SEG. 06		186.46

SEGMENT 06 TOTAL

F/R LBR

540.00 * 726.46 T



79536

Bill To:

PO BOX 429

MERKEL TX

REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

SERVICE INVOICE

INVOICE NUMBER: LB97924 Invoice Date: 08-11-20

Due \$17,964.85

Make AA Model D6NXL VPAT Serial # *CATOOD6NPMLW00160 Equip No

Machine ID C41208 Meter Reading 1261.0 PSO/WO

Customer# PO#			PSO/WO			LB97924
8950685	P0 #	Doc Date	Salesman	Division	Store	Terms
	PO REQUIRED	07-13-20	099	G	02	2
Quantity	Item	Description		Unit Price		Fytension

REMOVE & INSTALL GUARD

1.00

1.00

7/21/20 - **DIAMOND ATTACHMENTS** - D6N TIER IV FINAL EROPSREAR SCREEN - REAR GLASS PROTECTION WITH CLEANING DOORS REPAIR PROCESS COMMENTS: ATTEMPTED TO REMOVE THE DOOR FROM THE GUARD TO ACCESS THE MOUNTING BOLTS THE DOOR WAS CRUSHED AND WOULD NOT OPEN USED TORCH TO CUT THE HINGES FOR THE DOOR WAS ABLE TO ACCESS AND REMOVE THE MOUNTING BOLTS FOR THE GUARD REMOVED THE BOLTS AND USED THE CRANE TO REMOVE THE GUARD REMOVED HARNESS TO THE LIGHTS AND REMOVED THE LIGHTS FROM THE DAMAGED GUARD

RECEIVED NEW GUARD USED CRANE TO LIFT ONTO MACHINE
INSTALLED MOUNTING BOLTS AND SECURED GUARD TO CAB
INSTALLED LIGHTS INTO NEW GUARD
INSTALLED HARNESSES TO THE LIGHTS AND PLUGGED INTO THE MACHINE INSTALLED MOUNTING BRACKET FOR ANTENNA 12 7X-7729 WASHER S 8T-4137 12 BOLT S 170-2062 GRID N 294-7160 GUARD AS

> TOTAL PARTS SEG. 07 F/R LBR SCREEN

N

1.42

58.74

940.38

.86

Go Paperless. Receive statements and invoices online 24/7. Register at www.warrencat.com/gopaperless

INBOUND FREIGHT

WE APPRECIATE YOUR BUSINESS. Your business is important to us and we strive to be your dealership of choice, if we did not meet your expectations, please call 866.2WARREN.

Terms of Payment: Unless specific terms of payment are stated above, which shall be the governing terms hereof, this invoice shall otherwise be due and payable in full 30 days from the Invoice date. Performance under this invoice along with jurisdiction and venue shall be in Midland County, Texas. Return parts must be accompanied by the packing list or this invoice. Refer to packing list for parts return and available at http://www.warrencat.com/terms-conditions or upon request.

17.04

10.32

58.74

940.38

1026.48 *

1485.00 *

2781.41 36.33



79536

BIII To:

PO BOX 429

MERKEL TX

REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

SERVICE INVOICE

INVOICE NUMBER: LB97924 Invoice Date: 08-11-20

Due \$17,964.85

Make AA Model D6NXL VPAT Serial # *CATOOD6NPMLW00160 Equip No Machine ID

C41208 Meter Reading 1261.0 PSO/WO

LB97924 Customer# PO# Doc Date Salesman 8950685 Division Store PO REQUIRED Terms 07-13-20 099 G Quantity 02 Item 2 Description Unit Price Extension

TOTAL MISC CHGS

SEG. 07

2817.74 *

SEGMENT 07 TOTAL

5329.22 T

REMOVE & INSTALL CONDENSER FAN

REPAIR PROCESS COMMENTS: REMOVED THE BOLTS SECURING THE OLD CONDENSER FANS AND THE DAMAGED RELAY INSTALLED NEW FANS ONTO THE NEW CONDENSER AND INSTALLED AND ROUTED ALL WIRING

3E-5239 RELAY A 484-8774

FAN AS (24 V

28.28 297.97

28.28 595.94

TOTAL PARTS

SEG. 08

624.22 *

SEGMENT 08 TOTAL

F/R LBR

540.00 * 1164.22 T

REMOVE & INSTALL AIR CONDITIONER CONDENSER

REPAIR PROCESS COMMENTS: EVACUATED THE FREON FROM THE A/C SYSTEM REMOVED THE LINES GOING TO THE A/C CONDENSER REMOVED THE MOUNTING BOLTS FOR THE CONDENSER AND REMOVED IT FORM THE MACHINE

INSTALLED THE NEW CONDENSER ONTO THE NEW MOUNTING PLATE AND SECURED IT INSTALLED THE CONDENSER ASSEMBLY ONTO THE MACHINE FOUND THERE WAS A BENT BRACKET TO SECURE THE CONDENSER BENT THE BRACKET SO THAT THE CONDENSER COULD BE



79536

BIII To:

PO BOX 429

MERKEL TX

REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

SERVI	CE INI	/OICE
CAULANCE	7E-WV	OICL

Invoice Date:

Make

INVOICE NUMBER: LB97924 08-11-20

Due \$17,964.85

AA Model D6NXL VPAT Serial # *CATOOD6NPMLW00160

Equip No Machine ID

C41208 Meter Reading 1261.0 **PSO/WO**

LB97924 Customer# PO # Doc Date Salesman 8950685 Division Store PO REQUIRED Terms 07-13-20 099 G 02 Quantity 2 Item Description **Unit Price** Extension

MOUNTED INSTALLED AND SECURED ALL BOLTS
INSTALLED THE A/C LINES USING NEW O-RINGS
SET THE A/C SYSTEM TO VACUUM TO REMOVE ALL AIR.
TESTED THE VACUUM ON THE SYSTEM TO MAKE SURE IT CHARGED THE SYSTEM WITH FREON AND TESTED TO MAKE

SURE IT BLOWS COLD INSTALLED NEW GUARDS AND COVERS ON THE A/C CONDENSER

1 5P-5673 79 126-8472 1 175-2539 1 199-7698	M SEAL STK N CM SEAL N CASE AS N COIL AS N	5.76 .29 328.15 996.54	5.76 22.91 328.15 996.54	
	TOTAL PARTS	SEG. 09	1353.36 *	
1.00	INBOUND FREIGHT	F/R LBR	810.00 * 19.67	
	TOTAL MISC CHGS	SEG. 09	19.67 *	
	SEGMENT 09 TOTAL		2183.03 T	

REMOVE & INSTALL HYDRAULIC HOSES/LINES

REPAIR PROCESS COMMENTS: REMOVED THE TWO LEAKING HYDRAULIC LINES GOING TO THE RIGHT SIDE TILT CYLINDER INSTALLED AND ROUTED THE NEW LINES USING NEW O-RINGS INSTALLED AND MOUNTED THE CLIP THAT SECURES THE

TWO LINES TESTED THE MACHINE TO ENSURE THERE WERE NO OTHER



79536

BIII To:

PO BOX 429

MERKEL TX

REMIT TO

WARREN CAT PO BOX 842116 DALLAS, TX 75284-2116

432.571.4242 (Credit Dept.) 866.2WARREN (Toll Free)

Ship To:

SERVICE INVOICE INVOICE NUMBER:

Invoice Date:

Make

LB97924 08-11-20

Due \$17,964.85

AA Model D6NXL VPAT Serial # *CAT00D6NPMLW00160

Equip No Machine ID C41208

Meter Reading 1261.0 **PSO/WO**

ustomer#	PO#				PSO/WO LB97			
950685	PO REQUIRED	Doc Date		Salesman	Division	Store	Terms	
Quantity	Item		7-13-20	099	G	02	2	
	NOTE:	Description			Unit Pric	STREET, SQUARE, SQUARE	Extension	
LEAK ALL 2 2 4 1 1 8	TESTED OK 6V-7687 8T-4184 8T-4223 112-7455 310-1502 3096932X	LOCKNUT BOLT WASHER HOSE AS HOSE OILCAT HYDRO, 1 G	S S S N N S L S	2. 2. 1. 109. 86. 15.	16 33 75 63	10	5.64 4.32 5.32 9.75 6.63 7.20	
		TOTAL PARTS		SEG. 10		33	8.86 *	
		SEGMENT 10 TO	TAL	F/R LBR		67: 101:	5.00 * 3.86 T	

TAX EXEMPTION LICENSE GOVT

Go Paperless. Receive statements and invoices online 24/7. Register at www.warrencat.com/gopaperless

Parts Labor \$4,980.53 Misc. \$10,125.00 Tax \$2,859.32 TOTAL

\$0.00 \$17,964.85

WE APPRECIATE YOUR BUSINESS. Your business is important to us and we strive to be your dealership of choice. If we did not meet your expectations, please call 866.2WARREN.

Terms of Payment: Unless specific terms of payment are stated above, which shall be the governing terms hereof, this invoice shall otherwise be due and payable in full 30 days from the invoice date. Performance under this invoice along with jurisdiction and venue shall be in Midland County, Texas. Return parts must be accompanied by the packing list or this invoice. Refer to packing list for parts return and available at http://www.warrencat.com/terms-conditions or upon request.